



DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-1484; Project Identifier MCAI-2022-00897-G; Amendment 39-22339; AD 2023-03-14]

RIN 2120-AA64

Airworthiness Directives; Schempp-Hirth Flugzeugbau GmbH Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Schempp-Hirth Flugzeugbau GmbH Model Duo Discus and Duo Discus T gliders. This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as the airbrake becoming blocked or jammed in an extended position during high airspeed due to an incorrect adjustment on the airbrake system. This AD requires repetitively inspecting the airbrake system and taking corrective action as necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-

2022-1484; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For service information identified in this final rule, contact Schempp-Hirth Flugzeugbau GmbH, Kребenstrasse 25, Kirchheim unter Teck, Germany; phone: +49 7021 7298-0; email: info@schempp-hirth.com; website: schempp-hirth.com.
- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2022-1484.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Schempp-Hirth Flugzeugbau GmbH Model Duo Discus and Duo Discus T gliders. The NPRM published in the *Federal Register* on November 22, 2022 (87 FR 71264). The NPRM was prompted by AD 2022-0138, dated July 7, 2022 (referred to after this as “the MCAI”), issued by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of

the European Union. The MCAI states that an instance of the airbrake becoming blocked or jammed in an extended position during high airspeed on a Duo Discus glider occurred due to an incorrect adjustment on the airbrake system. A review of the manufacturer's maintenance manual revealed more maintenance information is needed to maintain the airbrake system in a serviceable condition. Accordingly, the MCAI requires repetitive inspections of the airbrake system and, depending on findings, accomplishing corrective actions in accordance with existing Schempp-Hirth Flugzeugbau GmbH maintenance instructions or instructions received by contacting Schempp-Hirth Flugzeugbau GmbH.

This condition, if not detected and corrected, could lead to blockage or jamming of the airbrake and result in reduced control of the glider.

In the NPRM, the FAA proposed to require accomplishing the actions specified in the MCAI, except as discussed under "Differences Between this Proposed AD and the MCAI." The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1484.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the

FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information under 1 CFR Part 51

The FAA reviewed Schempp-Hirth Flugzeugbau GmbH Maintenance Information SHK-M-01-22 for the Duo Discus and Duo Discus T airbrake system, dated January 26, 2022, which specifies procedures for inspecting and adjusting the airbrake system.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES.

Differences Between this AD and the MCAI

The MCAI applies to Schempp-Hirth Flugzeugbau GmbH Model Duo Discus C gliders, and this AD does not because this model does not have an FAA type certificate.

The MCAI requires accomplishing applicable corrective action in accordance with approved Schempp-Hirth Flugzeugbau GmbH maintenance instructions or contacting Schempp-Hirth Flugzeugbau GmbH for approved instructions and accomplishing those instructions accordingly. This AD requires adjusting the airbrake system in accordance with a method approved by the FAA; EASA; or Schempp-Hirth Flugzeugbau GmbH's Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

The MCAI references incorporating maintenance tasks into the Schempp-Hirth Aircraft Maintenance Program (AMP) to ensure accomplishment of the tasks required in the MCAI. Because the AMP is not required by FAA regulations for U.S. operators of the affected gliders, this AD does not reference the AMP and the actions are contained within this AD.

Costs of Compliance

The FAA estimates that this AD affects 32 gliders of U.S. registry.

The FAA estimates the following costs to comply with this AD:

Estimated costs

Action	Labor Cost	Parts Cost	Cost per product	Cost on U.S. operators
Inspect airbrake system	2 work-hours x \$85 per hour = \$170	Not applicable	\$170 per inspection cycle	\$5,440 per inspection cycle

The FAA estimates the following costs to do any necessary actions that would be required based on the results of the inspection. The agency has no data to determine the number of gliders that might need this action:

On-condition costs

Action	Labor Cost	Parts Cost	Cost per product
Adjust airbrake system	4 work-hours x \$85 per hour = \$340	\$200	\$540

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2023-03-14 Schempp-Hirth Flugzeugbau GmbH: Amendment 39-22339; Docket No. FAA-2022-1484; Project Identifier MCAI-2022-00897-G.

(a) Effective Date

This airworthiness directive (AD) is effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(b) Affected ADs

None.

(c) Applicability

This AD applies to Schempp-Hirth Flugzeugbau GmbH (Schempp-Hirth) Model Duo Discus and Duo Discus T gliders, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2760, Drag Control System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as blocking or jamming of the airbrake. The FAA is issuing this AD to detect and correct such blockage or jamming of the airbrake system. The unsafe condition, if not addressed, could result in reduced control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 12 months after the effective date of this AD and thereafter at intervals not to exceed 12 months, inspect the airbrake system for smooth operation, for sufficient airbrake panel overlap, and for proper cockpit control adjustment in accordance with Section I, and either II or III, depending on your glider configuration, of Schempp-Hirth Flugzeugbau GmbH Maintenance Information SHK-M-01-22 for the Duo Discus and Duo Discus T airbrake system, dated January 26, 2022.

Note 1 to paragraph (g)(1): Schempp-Hirth Flugzeugbau GmbH Technical Note 396-21, dated January 26, 2022; and Schempp-Hirth Flugzeugbau GmbH Technical Note 890-17, dated January 26, 2022, contain information related to this subject.

(2) If, during any inspection as required by paragraph (g)(1) of this AD, any part of the airbrake system is not properly adjusted, before further flight, adjust the airbrake system in accordance with a method approved by the FAA; the European Union Aviation Safety Agency (EASA); or Schempp-Hirth's Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (i)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email.

(i) Additional Information

(1) Refer to EASA AD 2022-0138, dated July 7, 2022, for related information. This EASA AD may be found in the AD docket at regulations.gov under Docket No. FAA-2022-1484.

(2) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (j)(3) and (4) of this AD.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Schempp-Hirth Flugzeugbau GmbH Maintenance Information SHK-M-01-22 for the Duo Discus and Duo Discus T airbrake system, dated January 26, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Schempp-Hirth Flugzeugbau GmbH, Krehenstrasse 25, Kirchheim unter Teck, Germany; phone: +49 7021 7298-0; email: info@schempp-hirth.com; website: schempp-hirth.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on February 9, 2023.

Christina Underwood, Acting Director,
Compliance & Airworthiness Division,
Aircraft Certification Service.

[FR Doc. 2023-04049 Filed: 2/28/2023 8:45 am; Publication Date: 3/1/2023]